



Repair Procedure 

RP-11062-015

| | | | |
|----------------|--|----------|--|
| Subject: | IMPORTANT: TRW Mode Change and Hyundai/Kia | | |
| Make(s): | Model(s): | Year(s): | |
| Hyundai Kia | See chart below | 2014+ | |
| Sensor(s): | TRW Part Number(s): | | |
| Tool | Software Version | | |
| ALL | R53.0 and Older | | |

IMPORTANT NOTICE:

UPDATE YOUR TOOL TO R53.2 BEFORE REPAIRING HYUNDAI or KIA Vehicles!

Overview:

Beginning with **Model Year 2014** Hyundai Elantra and other Hyundai/Kia vehicles, the TPMS Wheel Sensor supplied by TRW changed. This new sensor behaves differently from the ones in previous model years. This technology change came before release without sufficient notification, therefore the tool software had to “catch up.” This new sensor features different modes and mode changing commands.

NOTE: When these sensors are triggered with old software, the mode is unnecessarily changed, causing a communication problem with the car. All other processes behave normally [triggering and relearn communications]. The mode change however causes the sensor to NOT communicate with the car. Currently the sensors CANNOT BE CHANGED BACK. Once the mode is changed, the sensors are not usable for any application.

Bartec corrected the mode change issue beginning with software release 53.0. However, if you have older software, the 2014 Elantra selection will unnecessarily change the mode. As always, make certain you are selecting the proper Make, Model and Year when setting up your tool.

With the release of 53.2, Bartec has introduced preventative measures to insure even if the wrong MMY is selected, the tool can detect these sensors and inhibit any unnecessary mode changing.




Repair Procedure 

RP-11062-015

Sensors Affected:

Locate Part Number here



Application:

| Make | Model | Year From | Year To | Latest OEM |
|---------|----------|-----------|---------|-------------|
| Hyundai | Elantra | 2014 | 2014 | 52933-3X205 |
| Hyundai | Tucson | 2014 | 2015 | 52933-2S410 |
| Hyundai | Tucson | 2016 | 2016 | 52933-C1100 |
| Kia | Forte | 2014 | 2015 | 52933-A7000 |
| Kia | Sportage | 2014 | 2015 | 52933-2S500 |

Next Steps:

Bartec is working with the sensor manufacture to establish a sensor recovery process [change the mode back to the original state using the TPMS tool]. This will be part of a future update.