



## Software Update

TSB #	SUBJECT	DATE
SRB-R56.1	Tool Software Patch R56.1	May 19, 2017
S/W VERSION[S]	TOOL[S] AFFECTED	
56.1.0	See Below	

### Overview

Software Update Patch 56.1 for Bartec USA TPMS Tools. This software patch has been released to correct part numbers for Dill OE and REDI sensor replacement parts listed on the tool. Together, Bartec and Dill completed an exhaustive review of the tool/sensor coverage in an effort to improve tool accuracy.

**NOTE:** this is the last update to be released on the Tech400Plus tools with serial numbers starting with "6". (Serial Numbers 603000-699999) (Last sold September of 2009)

Feature	Industry Exclusive	Benefit	400Plus	400SD	500	300PRO	400PRO
Updated and corrected part number coverage on tool for Dill OE Replacement Parts		Insure the correct TPM Part is being fitted when installing a new sensor	✓	✓	✓	✓	✓
Updated and corrected part number coverage on tool for Dill REDI sensor Replacement Parts		Insure the correct TPM Part is being fitted when installing a new sensor	✓	✓	✓	✓	✓

This update is functionally the same and with the same features as Software Version 56.0.