



TPMS Technical Service Bulletin



Repair Procedure 

RP-596-012

Applies To: Honda Drive After Relearn

August 15, 2012

Scope of this bulletin:

After sensor relearns in any Honda, the vehicle must be driven in order for the light to shut off.



Topics covered in this bulletin:

1. Honda Drive After Relearn

1. Honda Drive after Relearn

After sensor relearns, if the mill light is flashing in any Honda, the vehicle must be driven in order for the light to shut off. The vehicle must be driven because the sensors are looking for motion in order for the vehicle to see them. The speed and distance that have to be driven is different for every car, but the light should turn off in less than 10 miles.