



Software Update

TSB #	SUBJECT	DATE
SRB-R58.1	Tool Software Update 58.1 Software Patch	Nov 19, 2018
S/W VERSION	TOOL[S] AFFECTED	
58.1	Tech400SD, Tech500, Tech300Pro, Tech300ProC and Tech400Pro. See chart for specific improvements to the respective tools.	

OVERVIEW

Feature	Exclusive	Benefit	400SD	500	300PRO	300PROC	400PRO
Bug Fix: Subaru OBD COMMS		Corrected OBD COMMS for Subaru vehicles not working in R58.0	✓	✓	✓	✓	✓
Bug Fix: 2018 Toyota Tacoma Coverage		Corrected OE and Aftermarket Sensor coverage for the 2018 Toyota Tacoma	✓	✓	✓	✓	✓
Bug Fix: Placard Pressure Change coverage updated		Corrected the Make-Model-Year list for Placard Change Support		✓			✓
Bug Fix: JohnDow DVT sensor coverage updated		Corrected coverage for JohnDow DVT Sensors.	✓	✓	✓	✓	✓
Bug Fix: NAPA QWIK sensor coverage updated		Added NAPA QWIK sensor coverage back to the 400SD tools.	✓				
Coverage: BMW 2018/10 OE Part Number 36 10 6 887 140		Added sensor coverage with qualifiers to 2018 Early/Late and 2019 BMW Models.	✓	✓	✓	✓	✓
Bug Fix: Toyota Prius listed twice		Removed 1 selection from vehicle listing	✓	✓	✓	✓	✓
Bug Fix: Toyota/Lexus Loop Reset (ECU Reset)		Process worked on R58.0, but would show a "failure". Corrected software to correctly indicate a successful function.	✓	✓	✓	✓	✓
Bug Fix: Hyundai/Kia COMMS		Corrected OBD COMMS for Hyundai/Kia vehicles not working in R58.0	✓	✓	✓	✓	✓
Updated EZ-sensor coverage		Added support for Schrader EZ-sensor	✓	✓	✓	✓	✓

****NOTE: R58.1 will list placard coverage for 2010-12 Chevrolet Impala and 2014-18 Ram 3500 SRW. These are not supported in this release. To see what placard is supported, see chart below.**

Bug Fix: Subaru OBD COMMS

Corrected issues in R58.0 for earlier Subaru vehicles where OBD COMMS did not work in R58.0.

Bug Fix: 2018 Toyota Tacoma Coverage

Corrected OE and aftermarket sensor coverage for the 2018 Toyota Tacoma.



Software Update

Bug Fix: Placard Pressure Change

Coverage corrected to released vehicles. See Listing below for current coverage.

Year	Make	Model	Year	Make	Model
2017	Cadillac	Escalade	2008	Chevrolet	Suburban
2016	Cadillac	Escalade	2016	Chevrolet	Tahoe
2015	Cadillac	Escalade	2015	Chevrolet	Tahoe
2014	Cadillac	Escalade	2014	Chevrolet	Tahoe
2013	Cadillac	Escalade	2013	Chevrolet	Tahoe
2013	Chevrolet	Avalanche	2012	Chevrolet	Tahoe
2012	Chevrolet	Avalanche	2011	Chevrolet	Tahoe
2011	Chevrolet	Avalanche	2010	Chevrolet	Tahoe
2010	Chevrolet	Avalanche	2008	Chevrolet	Tahoe
2017	Chevrolet	Equinox	2017	Chevrolet	Traverse
2016	Chevrolet	Equinox	2016	Chevrolet	Traverse
2015	Chevrolet	Equinox	2015	Chevrolet	Traverse
2012	Chevrolet	Equinox	2014	Chevrolet	Traverse
2016	Chevrolet	Express	2013	Chevrolet	Traverse
2015	Chevrolet	Express	2012	Chevrolet	Traverse
2014	Chevrolet	Express	2013	Dodge	RAM 1500
2013	Chevrolet	Express	2009	Dodge	RAM 1500
2012	Chevrolet	Express	2008	Dodge	RAM 1500
2011	Chevrolet	Express	2007	Dodge	RAM 1500
2010	Chevrolet	Express	2013	Dodge	RAM 2500
2011	Chevrolet	HHR	2013	Dodge	RAM 3500 SRW
2010	Chevrolet	HHR	2013	Ford	F-150
2017	Chevrolet	Silverado 1500	2012	Ford	F-150
2016	Chevrolet	Silverado 1500	2011	Ford	F-150
2015	Chevrolet	Silverado 1500	2012	Ford	F-250 SD
2014	Chevrolet	Silverado 1500	2011	Ford	F-250 SD
2013	Chevrolet	Silverado 1500	2017	GMC	Acadia
2012	Chevrolet	Silverado 1500	2016	GMC	Acadia
2011	Chevrolet	Silverado 1500	2015	GMC	Acadia
2010	Chevrolet	Silverado 1500	2014	GMC	Acadia
2009	Chevrolet	Silverado 1500	2013	GMC	Acadia
2008	Chevrolet	Silverado 1500	2012	GMC	Acadia
2016	Chevrolet	Silverado 2500	2011	GMC	Acadia
2015	Chevrolet	Silverado 2500	2010	GMC	Acadia
2014	Chevrolet	Silverado 2500	2009	GMC	Acadia
2013	Chevrolet	Silverado 2500	2015	GMC	Savana
2012	Chevrolet	Silverado 2500	2014	GMC	Savana
2016	Chevrolet	Silverado 3500	2013	GMC	Savana
2015	Chevrolet	Silverado 3500	2012	GMC	Savana
2014	Chevrolet	Silverado 3500	2011	GMC	Savana
2013	Chevrolet	Silverado 3500	2010	GMC	Savana
2012	Chevrolet	Silverado 3500	2017	GMC	Terrain
2016	Chevrolet	Suburban	2016	GMC	Terrain
2015	Chevrolet	Suburban	2015	GMC	Terrain
2014	Chevrolet	Suburban	2012	GMC	Terrain
2013	Chevrolet	Suburban	2011	GMC	Terrain
2012	Chevrolet	Suburban	2010	GMC	Terrain
2011	Chevrolet	Suburban	2013	Jeep	Wrangler
2010	Chevrolet	Suburban	2010	Jeep	Wrangler
2009	Chevrolet	Suburban			

Bug Fix: JohnDow DVT sensor coverage updated

Corrected coverage for JohnDow DVT Sensors.

©2018, Bartec USA, LLC

Bartec USA Technical Support: [866]407-8767

Bartec makes commercially reasonable efforts to provide accurate and complete data in connection with our tools and our website, but the volume of data compiled and the variety of sources from which the data comes makes it impossible to warrant full accuracy or completeness of any kind. AS A RESULT, BARTEC DOES NOT WARRANT, AND SPECIFICALLY DISCLAIMS ANY WARRANTY, THAT OUR TOOLS, WEBSITE, AND/OR THE CONTENT CONTAINED THEREIN IS ACCURATE OR COMPLETE.





Software Update

Bug Fix: NAPA QWIK Sensor coverage updated

Added NAPA QWIK sensor coverage back to the 400SD tools.

Bug Fix: BMW 2018/10 OE Part Number 36 10 6 887 140

Added sensor coverage with qualifiers to 2018 Early/Late and 2019 BMW Models.

Bug Fix: Toyota Prius listed twice

Removed 1 selection from vehicle listing.

Bug Fix: Toyota/Lexus Loop Reset (ECU Reset)

Process worked on R58.0, but tool showed a "failure" message. R58.1 has corrected this false feedback to correctly indicate a successful function.

Bug Fix: Hyundai/Kia COMMS

Corrected OBD COMMS for Hyundai/Kia vehicles not working in R58.0

Bug Fix: Updated EZ-sensor coverage

Added coverage for Schrader EZ-sensor.